



**F** SENSOR CIRCUIT

TO **B**  
MAIN  
(OPERATION  
CONTROL)  
CIRCUIT  
(CN6002) ON  
SCHEMATIC  
DIAGRAM-10



**G** TRAY MOTOR CIRCUIT



**H** LOADING MOTOR CIRCUIT

TO **B**  
MAIN  
(OPERATION  
CONTROL)  
CIRCUIT  
(CN6003) ON  
SCHEMATIC  
DIAGRAM-10

